




KM822 KM1022 KM1222

Wiring Diagrams

1 Phase

Wiring Diagram
Automatic Kiln

Models:
KM822 / KM1022 / KM1222
1-Zone
1-Phase 2-Wire + G




MJH 1/21/11
W_7565

3 Phase

Wiring Diagram
Automatic Kiln

Models:
KM822 / KM1022 / KM1222
1-Zone
3-Phase 3-Wire + G



MJH 4/20/11
W_7569