

KM kiln underfires	Condition: Witness cones placed in the top, center, and bottom of kiln indicate that the whole kiln is underfiring	8.3f
		KM kilns
		Kmunderf.vsd

