



WIRING
DIAGRAM
W_8514

MODELS:

- KMT-1231 PK
(FUSED)
PHASE: 3 PHASE
WIRE: 3W+G

REV: B

04/24/18

