



WIRING
DIAGRAM
W_8518

SKUTT

MODELS:

- KMT-1627 PK LF
(FUSED)

PHASE: 3 PHASE

WIRE: 3W+G

REV: B

04/24/18

