



WIRING
DIAGRAM
W_8510

SKUTT

MODELS:

- KMT-714

PHASE: 1 PHASE

WIRE: 2W+N+G

REV: B

04/24/18

