KS kiln overfires


Condition:

Witness cones indicate that the kiln is firing more than one cone hotter than programmed or sitter cone.

8.6c

KS kilns

Overfire.vsd



in the mechnism that frees the button.