


Wiring Diagram

Automatic Kiln

Models:
GM1027/GM1227

Zone Control
3-Phase



MJH 12/14/05
W_7001